

Inspection Photos

Location Name: Razor 14-1143H Location ID 430061

Inspection Date: 8/13/2019



Photo 1 – Stockpile of impacted material from bermed lined containment. Free oil present.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources