

Inspection Photos August 9, 2019
Location Name: Champlin 248 Amoco B #1
NESE Section 31 – Township 2 South - Range 64 West
Adams County



Danford-Champlin #14-8



Tank Battery Looking north. Weeds.

Inspection Photos August 9, 2019
Location Name: Champlin 248 Amoco B #1
NESE Section 31 – Township 2 South - Range 64 West
Adams County



Tank Battery showing 1 – 300 BBL crude oil tank and 1 – 300 BBL produced water. Photo looking north. Very weedy.



Tank battery looking south..

Inspection Photos August 9, 2019
Location Name: Champlin 248 Amoco B #1
NESE Section 31 – Township 2 South - Range 64 West
Adams County



Treater and meter shed. Looking north.



Pump jack - wellhead. Photo looking south. Note weeds.