

Construction and Stormwater Inspection

August 14, 2019

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 457722

Inspection Document #: 697500444

Broomfield County, CO

NENE Section 9 T1S R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: UNITED PAD
Location ID: 457722



Photo 1. Photo taken from the northwestern location, facing South. Photo illustrates the perimeter ditch and berm BMP that has been installed around the entire perimeter of the location. At the time of this inspection, the perimeter BMP appears to be stabilized and in proper functioning condition during major construction activities (i.e., topsoil salvage operations).



Photo 2. Photo taken from the western location, facing South. See comments under Photo 1. Photo also illustrates the topsoil stockpile. Operator was conducting topsoil salvage operations at the time of this inspection.

Inspection Photos
Location Name: UNITED PAD
Location ID: 457722



Photo 3. Photo taken from the southwestern location, facing East. See comments under Photo 1.



Photo 4. Photo taken from the southeastern location, facing East. Photo illustrates a sediment trap installed in conjunction with the perimeter ditch and berm BMP.

Inspection Photos
Location Name: UNITED PAD
Location ID: 457722



Photo 5. Photo taken from the southeastern location, facing North. See comments under Photo 1.



Photo 6. Photo taken from the eastern location, facing West. Photo illustrates topsoil salvage operations in-process.

Inspection Photos
Location Name: UNITED PAD
Location ID: 457722



Photo 7. Photo taken from the northeastern location, facing West. See comments under Photo 1.



Photo 8. Photo taken from the northern location, facing Southwest. Photo illustrates a water truck on location during construction activities.

Inspection Photos
Location Name: UNITED PAD
Location ID: 457722



Photo 9. Photo taken from the northwestern location, facing West. Photo illustrates a culvert being installed along the roadside ditch for the access point to location.