

# Final Reclamation Inspection

August 14, 2019

Operator: BATES\* JAMES EDWARD - 6575

API #: 05-001-06796

Inspection Document #: 697500450

Adams County, CO

SESE Section 7 T1S R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: WIERMAN #1  
API #: 05-001-06796



**Photo 1.** Photo taken on May 13, 2019 from the tank battery, facing Northwest. Photo illustrates Operator has not performed all Final Reclamation activities at the Location at the time of this inspection.

Inspection Photos  
Location Name: WIERMAN #1  
API #: 05-001-06796



**Photo 2.** Photo taken on August 14, 2019 from the tank battery, facing West. Photo illustrates Operator has performed Final Reclamation activities but the location will remain in-process as it does not meet our vegetative standard and weed management is needed. Both undesirable and noxious weeds were observed.

Inspection Photos  
Location Name: WIERMAN #1  
API #: 05-001-06796




**Photo 3.** Photo taken on August 14, 2019 from the tank battery, facing North. See comments under Photo 2.

Inspection Photos  
Location Name: WIERMAN #1  
API #: 05-001-06796



**Photo 4.** Photo taken on August 14, 2019 from the tank battery. Photo illustrates a List B Colorado noxious weed, Musk thistle.

Inspection Photos  
Location Name: WIERMAN #1  
API #: 05-001-06796



**Photo 5.** Photo taken on August 14, 2019 from the tank battery, facing West. Photo illustrates reference vegetation that will be used in evaluation for vegetative standards under Rule 1004.