

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-08746
Date: 8-12-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Pipes stored on location.



Photo 3. View of the northeastern project area facing westward. Vegetation is largely weeds such as dense kochia.



Photo 4. View of Canada thistle (*Cirsium arvense*) infestation within the northeastern project area.