

Inspection Photos
Location Name: UPRC/Bernhardt Tank Battery
Location ID: 330137



Photo 1: Location



Photo 2: Centralized Tank Battery



Inspection Photos
Location Name: UPRC/Bernhardt Tank Battery
Location ID: 330137



Photo 3: Weeds



Photo 4: Weeds/Debris

Inspection Photos
Location Name: UPRC/Bernhardt Tank Battery
Location ID: 330137



Photo 5: Weeds/Debris



Photo 6: Debris

Inspection Photos
Location Name: UPRC/Bernhardt Tank Battery
Location ID: 330137



Colorado Oil and Gas Conservation Commission

Photo 7: Debris



Colorado Oil and Gas Conservation Commission

Photo 8: Debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: UPRC/Bernhardt Tank Battery
Location ID: 330137



Photo 9: Peeled BBLs sticker



Photo 10: Peeled BBLs stickers

