

Inspection Photos

API: 05-009-06684

Operator: WAULCO RESOURCES

Inspection Date: 8/14/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06684 | Date: 8/14/2019

Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06684 | Date: 8/14/2019

Inspection Photos



Photo 2. There is an open pit that can be a safety concern.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06684 | Date: 8/14/2019

Inspection Photos



Photo 3. West side of the location facing south. There is perimeter surface roughening around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06684 | Date: 8/14/2019

Inspection Photos



Photo 4. There is a lined pit filled with water.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06684 | Date: 8/14/2019

Inspection Photos



Photo 5. Topsoil has been salvaged and placed at the south and north side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06684 | Date: 8/14/2019