

Interim Reclamation and Stormwater Inspection

August 14, 2019

Operator: PETROSHARE CORPORATION- #10454

Location ID: 451646

Inspection Document #: 697500458

Adams County, CO

SESW Section 20 T1S R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Brighton Lakes /20-17
Location ID: 451646



Photo 1. Photo taken from the entrance of Location, facing Northeast. Photo illustrates a vehicle tracking device BMP.

Inspection Photos
Location Name: Brighton Lakes /20-17
Location ID: 451646



Photo 2. Photo taken from the entrance of Location, facing East. Photo illustrates a culvert installed along the roadside ditch. Operator shall stabilize both the inlet and outlet of the culvert.



Photo 3. Photo taken from the other end of the culvert (east-side), facing East. See comments under Photo 2.

Inspection Photos
Location Name: Brighton Lakes /20-17
Location ID: 451646



Photo 4. Photo taken from the central Location, facing West. Photo illustrates eight wells have spud the surface hole. Notification to run and cement casing was received in mid-July.

Inspection Photos
Location Name: Brighton Lakes /20-17
Location ID: 451646



Photo 5. Photo taken from the eastern Location, facing South. Photo illustrates the topsoil stockpile which has been temporarily stabilized with equipment tracking.

Inspection Photos
Location Name: Brighton Lakes /20-17
Location ID: 451646



Photo 6. Photo taken from the southeastern Location, facing Southwest. Photo illustrates the well location and retention area which is all within a cut area. A ditch and berm BMP has also been installed along the outer perimeter of the location.