

Inspection Photos
Location Name: [HSR-TEETS #3-29A](#)
Location ID: 331239



Photo 1 WH sign



Photo 2 weeds around loc.

Inspection Photos
Location Name: [HSR-TEETS #3-29A](#)
Location ID: 331239



Photo 3 weeds on access road to loc.