

Inspection Photos
Location Name: Cleveland #8:
Location ID: 332926



Photo 1 WH



Photo 2 Pump jack Loc. sign

Inspection Photos
Location Name: Cleveland #8:
Location ID: 332926



Photo 3 Stained soil under engine skid

Photo 4 stained soil under engine skid

Inspection Photos
Location Name: Cleveland #8
Location ID: 332926



Photo 5 stained soil around WH