

COGCC Inspection Photos.

API # 077-09552

Inspection # 696600495



Photo #1. Sign is posted at the entrance to location.

COGCC Inspection Photos.
API # 077-09552
Inspection # 696600495



Photo #2 Photo at entrance to location



Photo #3 Photo at entrance to location

COGCC Inspection Photos.
API # 077-09552
Inspection # 696600495



Photo# 4. Photo of Tank Battery



Photo #5. Photo of Wellheads.

COGCC Inspection Photos.
API # 077-09552
Inspection # 696600495



Photo#6. Wattle on west entrance to location has sediment moving over the top. Sediment trap and wattle need maintenance.



Photo#7. Wattle on west entrance to location has sediment moving over the top. Sediment trap and wattle need maintenance.

COGCC Inspection Photos.
API # 077-09552
Inspection # 696600495



Photo# 8. Sediment moving over the top of armoring of sediment trap and in need of maintenance, at west side of entrance to location.



Photo# 8. Sediment Trap in need of maintenance on west side of entrance access road. .