

UNOCAL GM 23-33

Location # 324117



Weeds around well.

UNOCAL GM 23-33 Location # 324117



Open port on dehydrator heat element with no cover.

UNOCAL GM 23-33

Location # 324117



Movement of sediment



Sediment gathering around dehydrator.

UNOCAL GM 23-33

Location # 324117



Riling of road and ditch. (Entrance of location)

UNOCAL GM 23-33

Location # 324117



Ditch from entrance to check dam.



Overwhelmed and damaged check dam at entrance.

UNOCAL GM 23-33 Location # 324117



Over whelmed and damaged check dam at entrance.

Sediment from check dam built up on vegetation.

UNOCAL GM 23-33

Location # 324117



Sediment over shoulder of road at entrance.



Sediment over edge of location at overwhelmed check dam.

UNOCAL GM 23-33 Location # 324117



Diversion ditch full of sediment and breach of ditch wall.



Breach of ditch wall.