

**Inspection Photos**  
**Location Name: Federal GM 41-8**  
**Location ID: 334794**  
**Inspection Date: August 8, 2019**



**Photo #1 – Aerial view of the location, cuttings trench is located within the red circle (GISOnline Maps).**



**Photo #2 – Location sign, cuttings can be seen in the background.**

**Inspection Photos**  
**Location Name: Federal GM 41-8**  
**Location ID: 334794**  
**Inspection Date: August 8, 2019**



**Photo #3 – View of cuttings trench looking southwest. Red / brown / dark brown soil in bottom of the trench is drilling mud.**



**Photo #4 - View of cuttings trench looking southeast. Red / brown / dark brown soil in bottom of the trench is drilling mud.**

