

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402147580

Date Received:

08/16/2019

Spill report taken by:

Araza, Steven

Spill/Release Point ID:

466667

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: <u>LARAMIE ENERGY LLC</u>	Operator No: <u>10433</u>	<b>Phone Numbers</b>
Address: <u>1401 SEVENTEENTH STREET #1401</u>		Phone: <u>(970) 8125311</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Lorne C Prescott</u>		Mobile: <u>(970) 2106889</u>
		Email: <u>lprescott@laramie-energy.com</u>

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402142236

Initial Report Date: 08/13/2019 Date of Discovery: 08/12/2019 Spill Type: Recent Spill

#### Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWSE SEC 31 TWP 7S RNG 97W MERIDIAN 6

Latitude: 39.399015 Longitude: -108.260245

Municipality (if within municipal boundaries): \_\_\_\_\_ County: GARFIELD

#### Reference Location:

Facility Type: OIL AND GAS LOCATION

☒ Facility/Location ID No 421296

Spill/Release Point Name: 28-10 Off load Facility

☐ No Existing Facility or Location ID No.

Number: \_\_\_\_\_

☐ Well API No. (Only if the reference facility is well) 05- -

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): >=1 and <5

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: Approx 120 gallons or about 3 bbls released

#### Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): \_\_\_\_\_

Weather Condition: Dry, 90 deg f

Surface Owner: FEDERAL

Other(Specify): \_\_\_\_\_

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

*As defined in COGCC 100-Series Rules*

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

During fluid transfer from Cascade Creek to this location Laramie staff observed the release of fluids. Transfer was shut-off/terminated. No fluids left the boundary of the location. The fluid was absorbed by the soil almost immediately, no fluids were recovered. Estimate of volume released is based on the area occupied by the spill. Area is estimated to be 0.5 inches in depth, 3 feet wide and 150 feet long. Soil sampling, analysis and additional delineation will be conducted on August 13 or 14.

**List Agencies and Other Parties Notified:**

**OTHER NOTIFICATIONS**

Date	Agency/Party	Contact	Phone	Response
8/13/2019	GARCO LGD	Kirby Wynn	-	Acknowledged
8/13/2019	BLM	Jim Byers	970-3192532	Acknowledged
8/13/2019	BLM	Scott Hall	970-2443009	Acknowledged

Was there a Grade 1 Gas Leak associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Grade 1 Gas Leak Report Form 44: \_\_\_\_\_

Was there a reportable accident associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: \_\_\_\_\_

**SPILL/RELEASE DETAIL REPORTS**

#1	Supplemental Report Date: 08/16/2019		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	3	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: \_\_\_\_\_

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

**A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit**

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 150 Width of Impact (feet): 3

Depth of Impact (feet BGS): 0 Depth of Impact (inches BGS): 0

How was extent determined?

Visual assessment at the time of release. See attached photographs. Conditions were extremely dry, the released fluid was absorbed by the soil rapidly. The release was observed by Laramie staff as it occurred and the flow was cut off almost immediately. Resultant release was approximately 120 gallons or 3 bbls.

Soil/Geology Description:

Map Unit Symbol 44

Depth to Groundwater (feet BGS) 50 Number Water Wells within 1/2 mile radius: 1

If less than 1 mile, distance in feet to nearest Water Well 1289 None ☐ Surface Water 311 None ☐

Wetlands \_\_\_\_\_ None ☒Springs \_\_\_\_\_ None ☒Livestock \_\_\_\_\_ None ☒Occupied Building \_\_\_\_\_ None ☒

Additional Spill Details Not Provided Above:

Sampling and deliniation has been conducted. Lab results and final deliniation diagram were not available at the time of this submittal.

**REQUEST FOR CLOSURE****Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**Basis for Closure: ☐ Corrective Actions Completed (documentation attached)☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: \_\_\_\_\_

**OPERATOR COMMENTS:**

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Lorne C PrescottTitle: reg&enviro compliance Date: 08/16/2019 Email: lprescott@laramie-energy.com**COA Type****Description**

--	--

**Attachment Check List****Att Doc Num****Name**

402147639	AERIAL PHOTOGRAPH
402147640	OTHER

Total Attach: 2 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)