

COGCC Inspection Photos.

API # 077-08680

Inspection # 696600505



Photo #1. Sign is posted at the entrance to location.

COGCC Inspection Photos.
API # 077-08680
Inspection # 696600505



Photo #2 Photo at entrance to location

Photo #3 Photo at entrance to location

COGCC Inspection Photos.
API # 077-08680
Inspection # 696600505



Photo# 4. Photo of Tank Battery



Photo #5. Photo of Wellheads.

COGCC Inspection Photos.
API # 077-08680
Inspection # 696600505



Photo#6. Photo at NW corner of location. Erosion sediment moving off location and choking out vegetation.



Photo#7. . Photo at NW corner of location. Erosion sediment moving off location and choking out vegetation.

COGCC Inspection Photos.
API # 077-08680
Inspection # 696600505



Photo #8. Photo at W side of location. Erosion sediment moving off location and choking out vegetation. BMP needs maintenance.



Photo #9. Photo at W side of location. Erosion sediment moving off location and choking out vegetation. BMP needs maintenance.

COGCC Inspection Photos.
API # 077-08680
Inspection # 696600505



Photo #10. Erosion sediment moving off location into a sediment trap and around the armoring. Sediment trap on S side of location, needs maintenance.



Photo #11. Erosion sediment moving off location into a sediment trap and around the armoring. Sediment trap on S side of location, needs maintenance.