

COGCC Inspection Photos.

API # 077-08666

Inspection # 696600507




Photo #1. Sign is posted at the entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

COGCC Inspection Photos.
API # 077-08666
Inspection # 696600507



Photo #2 Photo at entrance to location



Photo #3 Photo at entrance to location

COGCC Inspection Photos.
API # 077-08666
Inspection # 696600507



Photo# 4. Photo of Tank Battery



Photo #5. Photo of Wellheads.

COGCC Inspection Photos.
API # 077-08666
Inspection # 696600507



Photo#6. Photo at East side of location. Erosion sediment moving off location and choking out vegetation.



Photo#7. Photo at East side of location. Erosion sediment moving off location and choking out vegetation.

COGCC Inspection Photos.
API # 077-08666
Inspection # 696600507



Photo #8. Photo at East side of location. Erosion sediment moving off location and choking out vegetation.



Photo #9 Photo at East side of location. Erosion sediment moving off location and choking out vegetation.

COGCC Inspection Photos.
API # 077-08666
Inspection # 696600507



Photo #10. Erosion sediment moving off location into a sediment trap and through the armoring. Sediment trap is on the S side of location, needs maintenance.



Photo #11. Erosion sediment moving off location into a sediment trap and through the armoring. Sediment trap is on the S side of location, needs maintenance.

COGCC Inspection Photos.
API # 077-08666
Inspection # 696600507



Photo #12. Photo on South side of location. Erosion sediment moving off location and choking out vegetation.



Photo #13. Photo from South side of location. Erosion sediment moving off location and choking out vegetation.

COGCC Inspection Photos.
API # 077-08666
Inspection # 696600507



Photo #14 Erosion sediment moving onto location by tank battery. BMP not working and needs maintenance at time of inspection.



Photo #15 Erosion sediment moving onto location by tank battery. BMP not working and needs maintenance at time of inspection.