

Inspection Photos

Operator: Southland Royalty
Location/API #: 067-08899
Date: 8-14-2019



Photo 1. View of the southern project area from the southeastern corner facing westward.



Photo 2. View of Canada thistles within the eastern project area. Poor revegetation on this berm.



Photo 3. View of Canada thistle infestation within the western project area.