

## Inspection Photos Location #322493



1 location



2 location





## Inspection Photos Location #322493



**3 Previous inspection of unmarked flow line**



**4 marked flow line**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos Location #322493



5 Weeds on lease road



6 Weeds on lease road



## Inspection Photos Location #322493



**7 Weeds on lease road**

