

Inspection Photos

API: 05-071-09911

Operator: NATURAL RESOURCE GROUP

Inspection Date: 8/12/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09911 | Date: 8/12/2019

Inspection Photos



Photo 1. Facing northwest toward the location. There is no equipment on location. The location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09911 | Date: 8/12/2019

Inspection Photos



Photo 2. Facing northwest toward the location. Arrow points to cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09911 | Date: 8/12/2019

Inspection Photos



Photo 3. Facing northeast toward the location. The location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09911 | Date: 8/12/2019