

Inspection Photos

08/16/2019

Operator: NOBLE ENERGY INC - 100322

Location ID: 422755

Weld County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos

Operator Name: NOBLE ENERGY INC - 100322

Location ID: 422755



Photo 1: Photo taken from the access road, facing east. Photo shows noxious weeds (Canada thistle) has not been removed. Operator has failed to conduct sufficient and ongoing noxious weed management.



Photo 2: Continued from photo 1. Photo shows Canada thistle has reached maturity and are dispersing seed. Operator has failed to conduct sufficient and ongoing noxious weed management.