

Inspection Photos
Location Name: Suckla Brown unit #1
Location ID: 317651



Photo #1 Location sign



Photo #2 WH

Inspection Photos
Location Name: Suckla Brown unit #1
Location ID: 317651



Photo #3 Stained soil around WH. Mechanical issue 1"
tubing valve appears to be leaking