

Inspection Photos
Location Name: Suckla Brown unit #12
Location ID:318307



Photo #1 Tall weeds down center of Access Rd.



Photo #2 WH sign

Inspection Photos
Location Name: Suckla Brown unit #12
Location ID:318307



Photo # 3 pump jack

Photo #4 trash on loc.

Inspection Photos
Location Name: Suckla Brown unit #12
Location ID:318307



Photo # 5 Stained soil around WH