

Inspection Photos
Location Name: Suckla Brown Unit #13
Location ID: 318308



40.06554, -104.86991,
08/19/20

Photo #1 Access Road Over grown with weeds



40.06726, -104.86968, 49
08/19/20

Photo #2 WH Sign



Inspection Photos
Location Name: Suckla Brown Unit #13
Location ID: 318308



Photo #3 Well is TA, production equip. has been removed since 2016.



Photo #4 Unused equip. Electric control box and PU cement base

Inspection Photos
Location Name: Suckla Brown Unit #13
Location ID: 318308



Photo #5 Unused equip. Electric panel control removed from box breaker box



Photo #6 Weeds overgrown on location within deadman