

Inspection Photos
Operator: Southland Royalty
Location/API #: 067-08660
Date: 8-14-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the northern fill slope from the northwestern edge facing eastward.



Photo 3. View of the reference area north of the well pad facing northeastward.