

Inspection Photos
Operator: BP America
Location/API #: 067-08709
Date: 8-19-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of southern fill slope from the southeastern corner facing westward. Irrigated crop field in background is reference area vegetation.



Photo 3. View of Canada thistles (*Cirsium arvense*) within the northeastern project area.