

Inspection Photos
Operator: BP America
Location/API #: 067-07188
Date: 8-19-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of southern fill slope from the southeastern corner facing westward.



Photo 3. View of reference area vegetation facing southward.