

Final Reclamation Inspection

August 14, 2019

Operator: VERDAD RESOURCES LLC - #10651

Location ID: 441850

Inspection Document #: 697500470

Weld County, CO

NWNE Section 26 T1N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Drake /01N-65W-26
Location ID: 441850



Photo 1. Photo taken from the northern location, facing Southeast. Photo illustrates Operator has performed final reclamation activities per the previous field inspection report.

Inspection Photos
Location Name: Drake /01N-65W-26
Location ID: 441850



Photo 2. Photo taken from a portion of the access road, facing West. See comments under Photo 1.