

Inspection Photos
Operator: BP America
Location/API #: 067-08724
Date: 8-19-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of eastern fill slope facing northward.



Photo 3. View of musk thistles that appear to be chemically treated.