

Inspection Photos
Location Name: Kiyota #1
Location ID: 318523



40.0892, -104.83704, 48
08/20/20

Photo#1 Well Head



40.08924, -104.83699, 48
08/20/20

Photo #2 Well Head sign


Inspection Photos
Location Name: Kiyota #1
Location ID: 318523



Photo#3 Service valve appears closed

Photo #4 Service valve appears closed

Inspection Photos
Location Name: Kiyota #1
Location ID: 318523



Photo#5 Misc. Greenhouse parts around Wel head

Photo #6 Misc. greenhouse parts around Wellhead