

Construction and Stormwater Inspection

August 19, 2019

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462919

Inspection Document #: 697500484

Weld County, CO

SESE Section 21 T11N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Little Lady 21 /South Well Pad

Location ID: 462919



Photo 1. Photo taken from the entrance of location, facing Northwest.

Inspection Photos
Location Name: Little Lady 21 /South Well Pad
Location ID: 462919



Photo 2. Photo taken from the entrance of location, facing North. Photo illustrates a vehicle tracking device BMP.



Photo 3. Photo taken from the entrance of the well location, facing South. Photo illustrates a vehicle tracking device BMP in conjunction with a ditch BMP.

Inspection Photos
Location Name: Little Lady 21 /South Well Pad
Location ID: 462919



Photo 4. Photo taken from the southeastern location, facing West. See comments under Photo 3.



Photo 5. Photo taken from the southwestern location, facing North. See comments under Photo 3.

Inspection Photos
Location Name: Little Lady 21 /South Well Pad
Location ID: 462919



Photo 6. Photo taken from the northwestern location, facing East. Photo illustrates the topsoil stockpile.



Photo 7. Photo taken from the northwestern location, facing East. See comments under Photo 6.

Inspection Photos

Location Name: Little Lady 21 /South Well Pad

Location ID: 462919



Photo 8. Photo taken from one of the wells. Photo illustrates a potential safety hazard to both people and wildlife. Operator indicated that cellar covers were ordered.