

Inspection Photos
Location Name: North York #13-12-3
Location ID: 320313



Photo 1 Well appears to be in the P&A process



Photo 2 Crude oil tank placard has been replaced and tank appears to have been drained.