

**Inspection Photos**  
**Location Name: Shable USX AB 11-3-TB**  
**Location ID: 433229**



**Photo 1 – Unused Dirt piled up on the Westside of location**



**Photo 2 – Unused Tubing Strings on the Eastside of Location**