

Inspection Photos

Location Name: SOONER UNIT-68N58W /28SENW

Location #: 330480



Photo #1

Sooner Unit 28-6-1 (05-123-19173) Wellsite
Temporarily Abandoned | TA
Bradenhead NOW appears plumbed to surface
Stained soil appears mitigated
Unused Equipment remains on site
prior insp.



Photo #2

Sooner Unit 28-6-1 Wellsite
Temporarily Abandoned | TA
Unused Equipment: NOW removed

Inspection Photos

Location Name: SOONER UNIT-68N58W /28SENW

Location #: 330480



Photo #3

Sooner Unit 28-6-1 Wellsite
Temporarily Abandoned | TA
Well sign



Photo #4

Sooner Unit Battery | Facility
from recent insp.