

Inspection Photos
Location Name: Sheldon Sickler #2
Location ID: 317693



Photo #1 Weeds growing on access road



Photo #2 Wellhead sign, weeds growing around wellhead



Inspection Photos
Location Name: Sheldon Sickler #2
Location ID: 317693



Photo #3 Weeds growing around wellhead



Photo #4 Control panel appears to be shut off

Inspection Photos
Location Name: Sheldon Sickler #2
Location ID: 317693



Photo #5 Weeds cleared from produced water tank



Photo #6 Weeds cleared from around separator

Inspection Photos
Location Name: Sheldon Sickler #2
Location ID: 317693



Photo #7 Tank battery sign



Photo #6 Weeds cleared from around crude oil tank