

Inspection Photos
Location Name: Sheldon Sickler#1
Location ID: 317661



Photo #1 Weeds growing on access road



Photo #2 Wellhead sign faded and illegible



Inspection Photos
Location Name: Sheldon Sickler#1
Location ID: 317661



Photo #3 Wellhead



Photo #4 Valves appear closed

Inspection Photos
Location Name: Sheldon Sickler#1
Location ID: 317661



Photo #5 Weeds around Electrical panel, Panel appears to be shut off

Photo #6 Weeds around pump jack

Inspection Photos
Location Name: Sheldon Sickler#1
Location ID: 317661



Photo #7 Weeds around electrical transformers