

Inspection Photos  
Location Name: Martin T. Hart #3  
Location ID: 318872



Photo #1 Wellhead



Photo #2 Wellhead sign

Inspection Photos  
Location Name: Martin T. Hart #3  
Location ID: 318872



Photo #3 Control panel appears to be turn

Photo #4 Pump jack

Inspection Photos  
Location Name: Martin T. Hart #3  
Location ID: 318872



Photo #5 Tank battery sign

Photo #6 Tank Battery