

**Inspection Photos**  
**Location Name: LILLI UNIT-68N58W /3SENW**  
**Location #: 327020**



**Photo #1**  
**Lilli Unit 6-3 (05-123-14017) UIC - Injection Wellsite**  
**UIC Annual Inspection**  
**Not Injecting - Gas**  
**Temporarily Abandoned | TA**  
**Weeds**



**Photo #2**  
**Lilli Unit 6-3 UIC - Injection Wellsite**  
**Weeds**

**Inspection Photos**  
**Location Name: LILLI UNIT-68N58W /3SENW**  
**Location #: 327020**



**Photo #3**  
**Lilli Unit 6-3 UIC - Injection Wellsite**  
**Temporarily Abandoned | TA**  
**Tbg. Press: 340#**



**Photo #4**  
**Lilli Unit 6-3 UIC - Injection Wellsite**  
**Temporarily Abandoned | TA**  
**Csg. Press: (-1#)**

**Inspection Photos**  
**Location Name: LILLI UNIT-68N58W /3SENW**  
**Location #: 327020**



**Photo #5**  
**Lilli Unit 6-3 UIC - Injection Wellsite**  
**Temporarily Abandoned | TA**  
**Bradenhead Press: (-1#)**



**Photo #6**  
**Lilli Unit Gas Plant | UIC - Injection Facility**  
**Facility Sign | Entrance**

**Inspection Photos**  
**Location Name: LILLI UNIT-68N58W /3SENW**  
**Location #: 327020**



Colorado Oil & Gas Conservation Commission  
40.68393, -103.87695, 1410.0m, 49°  
08/21/2019 03:45:38 PM

**Photo #7**

**Lilli Unit** Gas Plant | UIC - Injection Facility  
**Facility view**



Colorado Oil & Gas Conservation Commission  
40.68431, -103.87451, 1433.0m, 79°  
08/21/2019 03:21:25 PM

**Photo #8**

**Lilli Unit** Gas Plant | UIC - Injection Facility  
**Gas Injection Compressor | Discharge line**

**Inspection Photos**  
**Location Name: LILLI UNIT-68N58W /3SENW**  
**Location #: 327020**



**Photo #9**

**Lilli Unit** Gas Plant | UIC - Injection Facility  
**Gas Injection discharge line header**



**Photo #10**

**Lilli Unit** Gas Plant | UIC - Injection Facility  
**Gas Injection discharge line header**  
**Final stage to UIC wells.**