

Inspection Photos

API: 071-09402

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/21/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09402 | Date: 8/21/2019

Inspection Photos



Photo 1. Facing southeast along the access road approved for variance to remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09402 | Date: 8/21/2019

Inspection Photos



Photo 2. Facing east along the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09402 | Date: 8/21/2019

Inspection Photos



Photo 3. Facing east toward the location. Perennial vegetation has fully established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09402 | Date: 8/21/2019

Inspection Photos



Photo 3. There is an area at the south top side of the location and at the bottom fill slope which has noxious weeds (Canada thistle).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources