

Inspection Photos

API: 071-08103

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/21/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08103 | Date: 8/21/2019

Inspection Photos



Photo 1. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08103 | Date: 8/21/2019

Inspection Photos



Photo 2. There is an area at the east side of the location which has noxious weeds (Common mullein).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08103 | Date: 8/21/2019

Inspection Photos



Photo 3. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08103 | Date: 8/21/2019