

Inspection Photos

API: 071-08588

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/21/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08588 | Date: 8/21/2019

Inspection Photos



Photo 1. Facing east at the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08588 | Date: 8/21/2019

Inspection Photos



Photo 2. Facing east along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08588 | Date: 8/21/2019

Inspection Photos



Photo 3. Facing east toward the location. There is exposed rock along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08588 | Date: 8/21/2019

Inspection Photos



Photo 4. Facing south toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08588 | Date: 8/21/2019

Inspection Photos



Photo 5. Facing northeast toward the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08588 | Date: 8/21/2019

Inspection Photos



Photo 6. There is erosion along the cutslope at the north side of the location near the shallow pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08588 | Date: 8/21/2019

Inspection Photos



Photo 7. There is a guy line anchor at the northwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08588 | Date: 8/21/2019