

Inspection Photos
Operator: BP America
Location/API #: 067-07431
Date: 8-19-2019



Photo 1. View of the project area from the southeastern corner facing center. Pinyon juniper, reference area shown in background.



Photo 2. View of southern fill slope facing westward.



Photo 3. View of Dense kochia growing on the access road.