

Inspection Photos
Location Name: Jeanie AB 10-01R
Location ID: 430706



Photo 1 – Pumping Unit, Stained Soil at Wellhead



Photo 2 – Unused Tubing

Inspection Photos
Location Name: Jeanie AB 10-01R
Location ID: 430706



Photo 3 – Unused Pollution Pot lid



Photo 4 – Unused Pollution Pot lid



Inspection Photos
Location Name: Jeanie AB 10-01R
Location ID: 430706




Photo 5 – Unused Wellhead Parts