

Inspection Photos
Operator: BP America
Location/API #: 067-08897
Date: 8-21-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward.



Photo 3. View of reference area vegetation facing southward.