

Interim Reclamation Inspection

August 21, 2019

Operator: K P KAUFFMAN COMPANY INC - 46290

API: 05-123-09121

Inspection Document #: 697500513

Weld County, CO

NWSW Section 18 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HICKS #13-18 Tank battery

API: 05-123-09121



Photo 1. Photo taken from the tank battery sign.

Inspection Photos

Location Name: HICKS #13-18 Tank battery

API: 05-123-09121



Photo 2. Photo taken from the tank battery location, facing Northeast. Photo illustrates the Operator has failed to control and manage weeds.

Inspection Photos
Location Name: HICKS #13-18 Tank battery
API: 05-123-09121



Photo 3. Photo taken from the tank battery location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: HICKS #13-18 Tank battery
API: 05-123-09121



Photo 4. Photo taken from the tank battery location, facing East. See comments under Photo 2.