

Inspection Photos
Location Name: Cleveland #2
Location ID: 332884



Photo #1 Wellhead



Photo #2 Wellhead sign

Inspection Photos
Location Name: Cleveland #2
Location ID: 332884



Photo #3 Weeds growing around Wellhead

Photo #4 Valves appear to be closed

Inspection Photos
Location Name: Cleveland #2
Location ID: 332884



Photo #5 Service lines appear to be disconnected And capped

Photo #6 valve appears to be closed