

Inspection Photos
Location Name: B B DRAW H 4-1 J
Location ID 318989



Photo 1 – Location sign



Photo 2 – Location photo

Inspection Photos
Location Name: B B DRAW H 4-1 J
Location ID 318989



Colorado Oil and Gas Conservation Commission
40.25948, -104.66254, 4768.3ft, 42°
08/16/2019 11:37:50 AM

Photo 3 – Location photo



Colorado Oil and Gas Conservation Commission
40.25953, -104.66315, 4775.9ft, 228°
08/16/2019 11:34:53 AM

Photo 4 – Tinhorn and produced water vault

Inspection Photos
Location Name: B B DRAW H 4-1 J
Location ID 318989



Photo 5 – Erosion along berm surrounding tank



Photo 6 – Erosion next to produced water vault