

Inspection Photos

API: 05-071-06218

Operator: MERIDIAN OIL INC

Inspection Date: 8/22/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06218 | Date: 8/22/2019

Inspection Photos



Photo 1. Facing west toward the location which has been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06218 | Date: 8/22/2019

Inspection Photos



Photo 2. Facing toward the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06218 | Date: 8/22/2019

Inspection Photos



Photo 3. Stormwater controls have been installed. Rock rip/rap was installed in the drainages.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06218 | Date: 8/22/2019

Inspection Photos



Photo 4. Facing west. Rocks have been placed to prevent vehicle entry. Main road continues past location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06218 | Date: 8/22/2019

Inspection Photos



Photo 5. Facing east back toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06218 | Date: 8/22/2019