

Inspection Photos

API: 05-071-07561

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 8/22/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07561 | Date: 8/22/2019

Inspection Photos



Photo 1. There are vehicle ruts and potholes on the main road near the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07561 | Date: 8/22/2019

Inspection Photos



Photo 2. There is oil in the engine skid and staining on the surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07561 | Date: 8/22/2019