

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-06948**  
**Date: 8-21-2019**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing westward.



Photo 3. View of reference area vegetation facing southward.