

Inspection Photos  
Operator: BP America  
Location/API #: 067-08880  
Date: 8-21-2019



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of the eastern fill slope from the northeastern corner facing southward.





Photo 3. View of reference area vegetation facing southward.